Work Orde September 30, 2												Page 1
Item ID: Revision ID:	D4172-10	AM		Accept					Setup			
Item Name: Start Date: Required Date: Reference:	Angle 9/30/10 10/08/10	Start Qty: 5.00 Req'd Qty: 5.00			Cust Item I Customer:	ID:				Stop		
Approvals:	Process Pla	an: Z	Date: <u></u>			ate:		I	Run	Start Stop		
Sequence ID/ Work Center I	D	Operation Description	·	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Rev	vision Nbr										
D4172	A											
				0.00				£/	50	ho	104	5
Small Fab Small Fab			nght as per dwg 663 to drill holes in angle, o oles	0.00 open to size as per dwg							•	
		QC5- Inspect part comp	leteness to step on W/O		70/01			(x)	<u> </u>	•		
QC Quality Control		Memo		0.00								

Chemical Conversion Coat per QSI005 4.1

0.00 BR 10-10-6

HandFinish

Hand Finishing

Memo

0.00

Dart Aerospace Ltd

W/O:			WO	RK ORDER CHA	NGES	,				
DATE	STEP	PRO	OCEDURE CHAN	IGE	1	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Categ	jory:	NCR:	Yes N	lo DQA	\:	_ Date: _	
	R	esolution:	Disposition	:	QA: N	VC Clo	sed:		Date: _	
NCR:		•	WORK ORDE	R NON-CONFOR	RMANCE ((NCR)				
DATE	STEP	Description of NC		Section B			Approval	Approval QC Inspector		
DAIL	SILF	Section A	Initial Action Des Chief Eng Chief E						Chief Eng	
					-					
							MA CONTRACTOR OF THE CONTRACTO			
		·								E
1					·					

NOTE: Date & initial all entries

^{*}H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Work Order ID 62424

September 30, 2010 7:59:31 AM



Page 2

Item ID:

D4172-10

Accept

Setup Start

Stop

Stop



Revision ID:

Item Name: Angle

Required Date: 10/08/10

Start Date: 9/30/10

Start Qty: 5.00

Req'd Qty: 5.00

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Date:

Run Start

Reject

Qty



Date:

SPC (Y/N):

0.00

0.00

Set Up/

Run Hours

Tool ID

Tool # Plan

Code

Accept Qty

Reject Number Insp. Stamp

Sequence ID/ **Work Center ID**

130

QC

Quality Control

Operation Description

QC3- Inspect Part Finish

Memo

10/10/05

140

Packaging Packaging

Identify as per dwg & Stock Location:

Memo

0.00

0.00

150

Memo

QC21- Final Inspection - Work Order Release

0.00

0.00

10/10/07 78) MF 10-06

Quality Control

Dart	Aero	ospa	ace	Ltd
_ ~			~~~	

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No		PAR #:	Fault Cate	egory:	NCR: Yes	No DQ	A :	Date: _	
	R	esolution:	Disposition	on:	_ QA: N/C Cld	sed:		Date: _	
NCR:		\	WORK ORE	DER NON-CONFORMA	NCE (NCR)			
DATE	STEP	Description of NC	Description of NC Corrective Action			Verific	ication Ap	Approval	Approval
	SILF	Section A	Initial Action Description Chief Eng Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector
						,			

NOTE: Date & initial all entries

[•] H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Picklist Print

September 30, 2010 7:59:31 AM

Work Order ID: 62424

D4172-10 Parent Item:

Parent Item Name: Angle



Start Date: 9/30/10

Start Qty: 5.00

Loc Code

Required Date: 10/08/10

Page 1

Required Qty: 5.00

IPP Rev:A 10.09.09 new issue DD verf:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D6203		Manufactured	No			100	f	8.7053	0.0625	0.328947	holo) ·	

Angle Extrusion

Comments:

Location Loc Qty 8.7053 MAT

45501 8.7053

Dart Aeros	pace Ltd	
W/O:		

N/O:		WORK ORDER CHANGES												
DATE	STEP	PRO	CEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector						
								,						
						<u>.l</u>								
Part No	•	PAR #:	Fault Category:	NCR: Yes	No DQ	A:	Date:							

NCR:			WORK ORDER NON-CONFORMANCE (NCR)													
		Description of NC		Corrective Action Section B	· · · · · · · · · · · · · · · · · · ·	Verification	Annroyal	A								
DATE	STEP	Section A			Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector								
				·												
					·											

NOTE: Date & initial all entries

^{*}H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

